



медь

coils
rullis
рулоны

varš

DIN 1787
1791
40500

| izmērs size размер mm x Format | svars weight вес kg/m ² | E-Cu C 1100 mīksts soft мягкий F20 | E-Cu C 1100 pusciets half hard полутвердый F25 | E-Cu C 1100 ciets hard твердый F30 | E-Cu C 1100 hard as rolled | SE-Cu C 10200 mīksts soft мягкий F20 | SE-Cu C 10200 ciets hard твердый F25 | SE-Cu C 10200 hard as rolled |
|---|---|---|---|---|----------------------------------|---|---|------------------------------------|
| 0,2 | • | • | • | | | | | |
| 0,25 | • | • | • | | | | | |
| 0,3 | • | • | • | | | | | |
| 0,4 | • | • | • | | | | | |
| 0,5 | • | • | • | | | | | |
| 0,6 | • | • | • | | | | | |
| 0,7 | • | • | • | | | | | |
| 0,8 | • | • | • | | | | | |
| 0,9 | • | | | | | | | |
| 1 | • | • | • | | | | | |
| 1,25 | • | • | • | | | | | |
| 1,5 | • | • | • | | | | | |
| 2 | • | • | • | | | | | |
| 2,5 | • | • | • | | | | | |
| 3 | • | | | | | | | |